



	Explosion	Rimant Fororing		Strote Labning for Damp ind.		Strote Labning for Damp ud.		Indstimming. Dampvædet Optise.		Indstimming. Dampvædet Optise.		Skæve værdier	Skæbent. Skæbent. Hænding				
		B	F	B	F	B	F	B	F	B	F						
	makr.	3,75+3,75	3,75+3,75	38+0	35+0	40	40	0,75	0,75	79	82	93	94	5	6	124	10
Strøm	50	"	"	13,5+12	12+12	39	40	3	3,5	50	51	80	82	15	18	76,5	6
	30	"	"	7,75+7,75	6,75+6,75	33,75	34,75	7	7,5	31	30	70	72	24	26	65,5	6
	20	"	"	5,75+5,75	5+5	32	32,75	12	12	21	19	64	64	31	32	61,75	4
	0	"	"	3,75+3,75	3,75+3,75	30,75	30,75	40	37	7	7	48	48	48	47	58,5	0
Sjænge	20	"	"	5,75+5,75	5+5	32	32,75	12	11	21	19	64	64	32	32	61,75	1
	30	"	"	8+8	7+7	34	35	6	6,5	31	29	71	72	24	25	66	4
	50	"	"	14+12	12+12	39	40	3	3	50	51	80	83	14	17	77	7
	makr.	"	"	34+0	35+0	40	40	0,75	0,75	77	83	92	94	5	7	120	28

vinkel 94° 17'  
 hål i stift 130 mm.  
 hål i stift 25,5 mm  
 Indelning ÷ 1,5